

yellow

October 27, 1982

Carolina Power and Light Company
ATTN: Mr. E. E. Utley
Executive Vice President
411 Fayetteville Street
Raleigh, NC 27602

Gentlemen:

Subject: Report Nos. 50-400/82-34 and 50-401/82-34

This refers to the routine safety inspection conducted by Mr. N. Merriweather of this office on October 12-15, 1982, of activities authorized by NRC Construction Permit Nos. CPPR-158 and CPPR-159 for the Shearon Harris facility and to the discussion of our findings held with Mr. G. L. Forehand, Director QA/QC, at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations or deviations were disclosed.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC's Public Document Room unless you notify this office, by telephone, within ten days of the date of this letter and submit written application to withhold information contained therein within thirty days of the date of this letter. Such application must be consistent with the requirements of 10 CFR 2.790(b)(1).

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

Original signed by Verrelli

D. M. Verrelli, Chief
Reactor Projects Branch 1
Division of Project and
Resident Programs

Enclosure:
See Page 2

October 27, 1982

Enclosure:
Inspection Report Nos. 50-400/82-34
and 50-401/82-34

cc w/encl:
R. M. Parsons, Project General Manager

bcc w/encl:
NRC Resident Inspector
Document Management Branch
State of North Carolina

RII
mm
NMerriweather:ht
10/22/82

RII
TE
TEConlon
10/24/82

RII
AR
ARHerdt
10/22/82

RII
AK
AKHardin
10/24/82

RII
CW
CWBurger
10/26/82

RII
DM
DMVerrelli
10/26/82