

yellow

November 17, 1982

Westinghouse Electric Corporation
ATTN: Mr. M. D'Amore, Manager
Columbia Plant
Nuclear Fuel Division
Drawer R
Columbia, SC 29250

Gentlemen:

Subject: Report No. 70-1151/82-21

This refers to the routine safeguards inspection conducted by Mr. G. A. Todd of this office on October 28 - November 2, 1982, of activities authorized by NRC License No. SNM-1107 at Westinghouse facility and to the discussions of our findings held with you and members of your staff at the conclusion of the inspection.

Areas examined during this inspection included your program for nuclear material control and accountability under the applicable provisions of Title 10, Code of Federal Regulations, Part 70, "Special Nuclear Material," and specific license conditions. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, performance tests, and observations by the inspectors.

Within the scope of this inspection, no violations or deviations were disclosed.

One new unresolved item resulted from this inspection and is discussed in the enclosed report. This item will be examined during subsequent inspections.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, activities involving safeguards and security measures are exempt from public disclosure; therefore, the enclosed report with the exception of the cover page, which is an inspection summary, will not be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

(original signed by A. F. Gibson)

A. F. Gibson, Chief
Technical Inspection Branch
Division of Engineering and
Technical Programs

Enclosures (See Page 2)

Westinghouse Electric Corporation

2

November 17, 1982

Enclosures:

1. Inspection Report No. 70-1151/82-21
(Exempt from Disclosure)
2. Inspection Summary
(Not Exempt)

bcc w/Inspection Summary:
State of South Carolina

bcc w/encls:
Document Management Branch
Chief of Safeguards Branch, DSRSI
Chief, Division of Safeguards
Licensing Branch, 881SS

bcc w/o encls:
License Fee Management Branch

RII
cc for
JBLankford:es
11/16/82

RII *AG*
for GLTroup
11/16/82

RII *AG*
for EJMAlpine
11/16/82

RII *AG*
AFGibson
11/16/82