

FEB 7 1991

Docket No. 50-237 Docket No. 50-249

License Nos. DPR-19; DPR-25

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Opus West 111 1400 Opus Place Downers Grove, 11 60515

Gentlemen:

02220008 910

SUBJECT: NOTICE OF VIOLATION (NRC INSPECTION REPORT NOS. 50-237/90028(DRSS); 50-249/90027(DRSS)

This refers to the routine safeguards inspection conducted by Mr. T. J. Madeda of this office on December 11 through 18, 1990 and January 2 through 9, 1991. The inspection included a review of activities authorized for your Dresden Nuclear Power Station, Units 2 and 3. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, is specified in the enclosed Notice of Violation (notice). We are concerned about the violations because security managers were aware of the issues, but either failed to effectively followup on resolving the issues or incorrectly analyzed the significance of the issues.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Part 73, Title 10, Code of Federal Regulations, Section 73.21(c)(2). This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, Enclosure 1 to this letter, our report of the inspection (Enclosure 2) and your response to the violations identified in Enclosure 1 to this letter will not be placed in

ARA INTO PARA PLAN Sep ration This

TIVE UNIVIA I UN Page Is Decontrolled

18

La Sol B INFORMATION



Commonwealth Edison Company

the NRC Public Document Room. Therefore, your statement of corrective action regarding the violations identified in Enclosure 1 should be submitted as a separate enclosure to your transmittal letter in the manner rescribed. The Non-Safeguards Information, Enclosure 3 (Allegation Review), will be placed in the Public Document Room.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

L. Robert Greger, Chief Reactor Programs Branch

Enclosures: 1. Notice of Violation 2.4 Inspection Reports No. 50-237/90028(DRSS) No. 50-249/90027(DRSS) (SAFEGUARDS INFORMATION) 3. Allegation Review cc w/enclosures: D. Galle, Vice President - BWR Operations T. Kovach, Nuclear Licensing Manager E. D. Eenigenburg, Station Manmer NRR/DRIS/SGB NRR/DRIS/S18 NRR/DLPC/PEB cc w/enclosures, w/o SAFEGUARD INFORMATION: DCD/DCB (RIDS) OC/LFDCB Resident Inspectors LaSalle, INTODIATION Dresden, Quad Cities S Manual Land Richard Hubbard J. W. McCaffrey, Chief, Public Utilities Division Robert Newmann, Office of Public Enclosure Contains Counsel, State of Illinois Center SAFEGUARDS INFORMATION Upon Separation Inis. RIII Page Is Decontrolled Greder 7 /91