

December 3, 1982

Mr. R.C. Haynes Director, Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION LICENSEE EVENT REPORT 82-031/03L-1 ER 100450 FILE 841-23 PLA-1422

Docket No. 50-387 License No. NPF-14

Dear Mr. Haynes:

Attached please find a copy of Licensee Event Report No. 82-031/03L-1. This event was determined to be reportable per Technical Specification 6.9.1.9.b. Revision 0 noted that differential pressure instrumentation indicated that Zone III of secondary containment was not maintained at the required vacuum. Additional events of a similar nature occurred prior to implementation of the design changes to produce a permanent solution. This revision lists the other events and explains the design changes.

H.W. Keiser

Superintendent of Plant-Susquehanna

DGM/cw

cc: A. Schwencer
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, DC 20555

G. Rhoads
Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

B21214C268 B212O3 PDR ADUCK 05000387 PDR

TER