TENNESSEE VALLEY AUTHORITY CHATTANOOGA, TENNESSEE 37401 1750 Chestnut Street Tower II December 10, 1982 Mr. James P. O'Reilly, Director

12 DEC 13 AND : 3.

U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE REPORT BFRO-50-260/82036

The enclosed report provides details concerning a continuous air monitor becoming inoperable. This report is submitted in accordance with Browns Ferry unit 2 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J/ Green

Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

TE 22