Docket ho. 50-341

The Detroit Edison Company ATTN: B. Ralph Sylvia Group Vice President Nuclear Operations 6400 North Dixie Highway Newport, MI 48166

Gentlemen:

This refers to the routine safety inspection conducted by Dr. J. E. House of this office on February 4-6, 1991, of activities at Fermi 2, authorized by NRC Operating License No. NFF-43 and to the discussion of our findings with Mr. R. McKeon and others of your staff at the conclusion of the inspection. Telephone discussions were held with members of your staff on February 8, 1991.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course . this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

L. Robert Greger, Chief Reactor Programs Branch

Enclosure: Inspection Report No. 50-341/91005(DRSS)

See Attached Distribution

9103040027 910222 PDR ADOCK 05000341 PDR

010026

Mouse/Jp

Schumacher

TEOL

## Distribution

CC w/enclosure:
D. R. Gipson, Assistant Vice
President & Manager Nuclear
Production
Patricia Anthony, Licensing
P. A. Marquardt, Corporate
Legal Department
DCD/DCB (RIDS)
OC/LFDCB
Resident Inspector, RIII
James R. Padgett, Michigan Public
Service Commission
Harry H. Voight, Esq.
Michigan Department of
Public Health
Monroe County Office of
Civil Preparedness
Fermi, LPM, NRR