

APPENDIX A

NOTICE OF VIOLATION

Philadelphia Electric Company
Peach Bottom Units 2 and 3

Docket/License: 50-277/DPR-44
50-278/DPR-56

As a result of the inspection conducted on October 21 - November 30, 1982, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 9, 1982 (47 FR 9987), the following violation was identified:

A.1 Technical Specification 3.14.B requires a continuous fire watch in the Diesel Generator area if the Diesel Generator Carbon Dioxide Fire Suppression System storage tank pressure is less than 280 psig.

Contrary to the above, from 9:45 a.m. to 3:45 p.m. on October 21, 1982, the Diesel Generator Building Carbon Dioxide Fire Suppression System storage tank pressure was less than or equal to 260 psig and there was no fire watch in the Diesel Generator area.

This is a Severity Level IV Violation (Supplement I) applicable to DPR-44 and DPR-56.

Pursuant to the provisions of 10 CFR 2.201, Philadelphia Electric Company is hereby required to submit to this office within 30 days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including for each violation: (1) the corrective steps which have been taken and the results achieved; (2) the corrective steps which will be taken to avoid further violations, and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

8212160486 821203
PDR ADOCK 05000277
Q PDR

OFFICE ▶
SURNAME ▶
DATE ▶