DEC 3 1982

Docket: 50-382/82-20

Louisiana Power and Light Company ATTN: L. V. Maurin, Vice President Nuclear Operations 142 Delaronde Street New Orleans, Louisiana 70174

Gentlemen:

This refers to the Systematic Assessment of Licensee Performance (SALP) Board Report of the Waterford Facility, Unit 3, Construction Permit CPPR-103. The SALP Board met on August 24, 1982, to evaluate the performance of the subject facility for the period July 1, 1981, through June 30, 1982. The performance analyses and resulting evaluation are documented in the enclosed SALP Board Report. These analyses and evaluation were discussed with you at your office in New Orleans, Louisiana, on October 20, 1982.

The performance of your facility was evaluated in the following functional areas: Containment and Other Safety-Related Structures; Piping Systems and Supports; Safety-Related Components; Fire Protection; Electrical Power Supply and Distribution; Instrumentation and Control Systems; Licensing Activities; Plant Operations Preparation; Security and Safeguards; Preoperational Testing; Surveillance; Audits, Reviews and Committee Activities; Initial Fuel Load Preparations; Chemistry/Radiochemistry; Radiation Protection; Effluent Control and Monitoring; Transportation of Radioactive Waste; and Radioactive Waste Management.

The SALP Board evaluation process consists of categorizing performance in each functional area. The categories which we have used to evaluate the performance of your facility are defined in Section II of the enclosed SALP Board Report.

During the meeting with J. W. Wyatt, you, and other members of your staff in New Orleans, Louisiana, on October 20, 1982, you were given the option of submitting comments concerning our evaluation of your facility by November 9, 1982.

8212200121 821203 PDR ADDCK 05000382 0 PDR

RPS-B war

12/ / /82

AME GLConstable gc. WACrossman GLMadsen

RPB1 war

12/ //82

S-B war

12/1 /82

NRC FORM 318 (10:80) NRCM 0240

169

OFFICIAL RECORD COPY

DRRP&EP

JGagliardo.

12/ - /82

201

## Louisiana Power and Light Company

-2-

Your letters, dated November 8 and November 16, 1982, which forwarded your comments, and the SALP Board Report appear as enclosures to this letter which issues the SALP Board Report as an NRC report. Your letters of November 8 and November 16, 1982, our letter of October 14, 1982, a copy of the 1982 SALP Report, and a copy of this letter will be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

Original Sigued By: Richard L. Bangart

John T. Collins Regional Administrator

Enclosure: Appendix - NRC Report 50-382/82-20

cc: Louisiana Power and Light Company Waterford-3 ATTN: D. B. Lester, Plant Manager P. O. Box B Killona, LA 70066

Louisiana Power and Light Company ATTN: F. J. Drummond, Project Manager 142 Delaronde Street New Orleans, LA 70174

T. F. Gerrets, QA Manager
(same address)

bcc to DMB (IEO1)

25

10

bcc distrib. by RIV: W. Crossman, RPS-B G. Constable, RRI J. Cummins, RRI RPB2 S. Black, NRR R. Stewart, RPS-A TPB Info. Systems RIV File C. Wisner, PAO Louisiana Div. of Rad. Control

NRC FORM 318 (10.80) NRCM 0240 OFFICIAL		RECORD COPY				
DATE	itaninina mananana	*****				
SURNAME	**************					
OFFICE	*****	*****				******