A REGULATION COMMISSION OF THE PROPERTY OF THE

UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011 8064

.RR 1 9 1994

Dockets: 50-498

50-499

Licenses: NPF-76

NPF-80

Houston Lighting & Power Company ATTN: William T. Cottle, Group

Vice President, Nuclear

P.O. Box 289

Wadsworth, Texas 77483

SUBJECT: NRC INSPECTION REPORT 50-498/94-19; 50-499/94-19 (NOTICE OF

VIOLATION)

This refers to the inspection conducted by Messrs. L. E. Ellershaw and V. G. Gaddy of this office on May 16-20, with in-office inspection through July 8, 1994. The inspection included a review of activities authorized for your South Texas Project Electric Generating Station, Units 1 and 2, facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report and included your inservice testing program for pumps and valves. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. The results of this inspection are documented on pages 1 and 2, in the enclosed report.

Based on the results of this inspection, certain licensed activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violation is of concern because it is indicative of a continuing problem with your corrective action program implementation.

During the inspection, two unresolved items were identified. One concerned the lack of a probing investigation into an identified concern regarding responsibilities and authority for designating the performance of a local leak rate test, and is addressed in Section 2.3.3 of the enclosed inspection report. The other concerned the possible failure to document entries into Technical Specification action statements, including the possibility that operations personnel were not cognizant of the need to document action statement entries when they were conducted in conjunction with regularly scheduled surveillance tests. This item is addressed in Section 2.4.2.1 in the enclosed inspection report.

During a July 7, 1994, engineering meeting in the Region IV office, Mr. Cloninger and his staff presented plans to address needed improvements in the inservice test program. These plans included a self-assessment of the program that was scheduled for later this calendar year. Please notify me if your understanding differs from ours.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Thomas P. Gwynn, Director Division of Reactor Safety

Enclosure:

Appendix - NRC Inspection Report 50-498/94-19; 50-499/94-19 w/Attachments

cc w/enclosure:

Houston Lighting & Power Company

ATTN: James J. Sheppard, General Manager

Nuclear Licensing

P.O. Box 289

Wadsworth, Texas 77483

City of Austin Electric Utility Department ATTN: J. C. Lanier/M. B. Lee 721 Barton Springs Road Austin, Texas 78704

City Public Service Board ATTN: K. J. Fiedler/M. T. Hardt P.O. Box 1771 San Antonio, Texas 78296

Newman & Holtzinger, P. C. ATTN: Jack R. Newman, Esq. 1615 L Street, NW Washington, D.C. 20036 Central Power and Light Company ATTN: G. E. Vaughn/T. M. Puckett P.O. Box 2121 Corpus Christi, Texas 78403

INPO Records Center 700 Galleria Parkway Atlanta, Georgia 30339-5957

Mr. Joseph M. Hendrie 50 Bellport Lane Bellport, New York 11713

Bureau of Radiation Control State of Texas 1100 West 49th Street Austin, Texas 78756

Office of the Governor
ATTN: Susan Rieff, Director
Environmental Policy
P.O. Box 12428
Austin, Texas 78711

Judge, Matagorda County Matagorda County Courthouse 1700 Seventh Street Bay City, Texas 77414

Licensing Representative Houston Lighting & Power Company Suite 610 Three Metro Center Bethesda, Maryland 20814

Houston Lighting & Power Company ATTN: Rufus S. Scott, Associate General Counsel P.O. Box 61867 Houston, Texas 77208

Shaw, Pittman, Potts & Trowbridge ATTN: Joseph R. Egan, Esq. 2300 N Street, N.W. Washington, D.C. 20037 E-Mail report to D. Sullivan (DJS)

bcc to DMB (IEO1)

L. Ellershaw V. Gaddy

bcc distrib. by RIV:

L. J. Callan Branch Chief (DRP/A) MIS System RIV File Project Engineer (DRP/A) R. Bachmann, OGC, MS: 15-B-18 D. Powers

Resident Inspector Leah Tremper, OC/LFDCB, MS: MNBB 4503 DRSS-FIPB G. F. Sanborn, EO Branch Chief (DRP/TSS)

RIV:RI:MB	RI:MB 15	C:M977	DD:DRS	D: DRPY M	D:DRS
LEEllershaw	VGGaddy	DAPowers	JLPellet	ABBeach	TPGwynn
07/17/94	07/11/94	07/14/94	07/18/94	07/18/94	07/19/94

E-Mail report to D. Sullivan (DJS)

bcc to DMB (IEO1)

bcc distrib. by RIV:

L. J. Callan Branch Chief (DRP/A) MIS System RIV File Project Engineer (DRP/A) R. Bachmann, OGC, MS: 15-B-18

D. Powers L. Ellershaw V. Gaddy

Resident Inspector Leah Tremper, OC/LFDCB, MS: MNBB 4503 DRSS-FIPB G. F. Sanborn, EO Branch Chief (DRP/TSS)

RIV:RI:MB	RI:MB	C:MBM	DD:DRS	D: DRPY 10	D:DRS
LEEllershaw	VGGaddy	-6	JLPellet	ABBeach	TPGwynn
07/17/94	07/17/94	07/14/94	07/18/94	07/18/94	07/19/94