

## LICENSEE EVENT REPORT

CONTROL BLOCK:  ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 F | L | S | L | S | 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 16 LICENSE NUMBER 25 26 27 28 29 30 31 32 33 34 35 36 37 CAT 38

CON'T  
REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 5 | 7 | 1 | 1 | 2 | 3 | 8 | 2 | 8 | 1 | 2 | 2 | 2 | 8 | 2 | 9  
50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal steady state operation the DDPS was declared inoperable.

0 3 | This resulted in a loss of the CEA pulse counting backup position

0 4 | indication and the linear heat rate monitor by incore detectors. Action

0 5 | was taken in accordance with T.S.3.1.3.3.d. Power was reduced to 82%

0 6 | until the DDPS was restored 1 hour and 50 minutes later. This is the 26th

0 7 | event involving the loss of the DDPS.

The loss of DDPS was software related and involved the loss of a constant value during core to program transfer.

1 2 |

1 2

Page 1 of 1

E (28) 9 9 (29) N/A A (31) OPERATOR OBSERVATION

ACTIVITY CONTENT  
RELEASED OR RELEASE  
AMOUNT OF ACTIVITY (35)  
N/A

LOCATION OF RELEASE (26)  
N/A

PERSONNEL EXPOSURES  
NUMBER      TYPES      DESCRIPTION 39

1 7  
7 8 9 10 11 12 13  
3 PERSONNEL INJURIES  
NUMBER DESCRIPTION 41

1 4  
7 3  
O O O 40 N/A

LOSS OF OR DAMAGE TO FACILITY **(4)**  
TYPE **(5)** DESCRIPTION **(6)**

NBC US\* ONLY

ISSUED BY **Z-42** DESCRIPTION **N/A**

NAME OF PREPARED — J. P. Brannin

PHONE (305) 465-3550 x427

8212300065 821122  
PDR ADOCK 05000335  
S PDR