

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
 /0/1/ /V/A/N/A/S/2/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT
 /0/1/ REPORT /L/ (6) /0/5/0/0/0/3/3/9/ (7) /1/2/1/3/8/2/ (8) /1/2/2/2/8/2/ (9)
 SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On December 13, 1982, with Unit 2 at 100% power, Fire Door S71-18 between the /
 /0/3/ / "2H" Emergency Diesel Generator Room and the Turbine Building would not latch and /
 /0/4/ / lock. Since a fire watch was immediately posted the public health and safety /
 /0/5/ / were not affected. This event is contrary to T.S. 3.7.15 and reportable to /
 /0/6/ / T.S. 6.9.1.9.b. Degradation of fire doors between the Emergency Diesel Room and /
 /0/7/ / the Turbine Building is a recurring event due to the differential pressure during /
 /0/8/ / diesel operation. /

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
/0/9/ /A/B/ (11)	/E/ (12)	/B/ (13)	/X/X/X/X/X/X/ (14)	/Z/ (15)	/Z/ (16)
LER/RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.
(17)	/8/2/	/-/ /0/8/2/ /	/0/3/	/L/	/-/ /0/

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
/E/ (18)	/X/ (19)	/Z/ (20)	/Z/ (21)	/0/0/0/0/ (22)	/N/ (23)	/N/ (24)	/A/ (25)	/C/1/7/5/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / Fire Door S71-18 would not latch because the latch was sticking. The latch was /
 /1/1/ / adjusted, lubricated and the operability of the fire door verified. Design /
 /1/2/ / modifications to the fire doors between the Emergency Diesel Room and the Turbine /
 /1/3/ / Building are being pursued. /
 /1/4/ /

FACILITY STATUS	%POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
/1/5/ /E/ (28)	/1/0/0/ (29)	/ NA / (30)	/A/ (31)	/ Operator Observation /
ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)	
/1/6/ /Z/ (33)	/Z/ (34)	/ NA /	/ NA /	
PERSONNEL EXPOSURES	NUMBER	TYPE	DESCRIPTION (39)	
/1/7/ /0/0/0/ (37)	/Z/ (38)	/ NA /	/	
PERSONNEL INJURIES	NUMBER	DESCRIPTION (41)		
/1/8/ /0/0/0/ (40)	/ NA /	/		
LOSS OF OR DAMAGE TO FACILITY	TYPE	DESCRIPTION (43)		
/1/9/ /Z/ (42)	/ NA /	/		
PUBLICITY ISSUED	DESCRIPTION (45)			
/2/0/ /N/ (44)	/ NA /			

NAME OF PREPARER W. R. CARTWRIGHT PHONE (703) 894-5151
 NRC USE ONLY
 8212300291 821222 PDR ADOCK 05000339 PDR