Docket File



NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20856

March 14, 1991

Docket Nos. STN 50-45., STN 50-455 and STN 50-456, STN 50-457

Mr. Thomas J. Kovach Nuclear Licensing Manager Commonwealth Edison Company-Suite 300 OPUS West III 1400 OPUS Place Downers Grove, Illinois 60515

Dear Mr. Kovach:

SUBJECT: SUPPLEMENTAL SAFETY EVALUATION OF BYRON STATION, UNITS NOS. 1 AND 2
AND BRAIDWOOD STATION, UNIT NOS. 1 AND 2; RESPONSE TO THE STATION
BLACKOUT PILLE (TAC NOS 68522 68523 68515 AND 68516)

BLACKOUT RULE (TAC NOS. 68522, 68523, 68515 AND 68516)

The NRC staff's Safety Evaluation (SE) pertaining to the Commonwealth Edison Company's (CECo) initial responses to the Station Blackout (SBO) Rule, 10 CFR 50.63, was transmitted to you by letter dated August 6, 1990. The staff found your proposed method of coping with an SBO to be unacceptable, primarily because the proposed AAC source did not have sufficient excess capacity to qualify as an AAC source.

CECo responded to this concern and the NRC staff's other recommendations by letter dated November 2, 1990.

CECo re-evaluated the loss of offsite power (LOOP) loads and the SBO loads using equipment design requirements for the loads as opposed to overly conservative motor ratings. Also, actual motor efficiencies rather than assumed efficiencies were used for the larger motor loads. You stated that Table 8.3-5 of the Updated Final Safety Analysis Report (UFSAR) would be revised to reflect these changes and to correct some errors that were identified during the SBO review. Based on the load re-evaluation and your commitment to revise the UFSAR, the staff now finds that the proposed AAC power source qualifies as an excess capacity AAC source consistent with the SBO rule and associated guidance.

CECn's response to each of the staff's recommendations has been evaluated in the enclosed Supplemental Safety Evaluation (SSE) and found to be acceptable. The staff therefore concludes that your proposed method of coping with an SBO con'orms to the SBO rule. However, CECo should maintain all documentation

OFO!

supporting the SBO submittals available for further inspection and assessment as may be undertaken by the NRC to audit conformance to the SBO rule. This closes TAC Nos. 68522, 68523, 68515 and 68516.

Sincerely.

Original Signed By:

Robert M. Pulsifer, Project Manager Project Directorate III-2 Division of Reactor Projects - III/IV/V Office of Nuclear Reactor Regulation

Enclosure: Supplemental Safety Evaluation

cc w/enclosure: See next page

DISTRIBUTION
Doc-et File
NRC & Local PDRs
PDIII-2 r/f
BBoger, 14A2
JZwolinski
CMoore
RPulsifer
AHsia
UGC
EJordan, MNBB 3701
AToalston, 7E4
ACRS (10)
Plant File
WShafer, RIII

			.1	
OFC : EARPOXING	:PM:PDIII-2	:PM:PDIII-2	:D:PDILY	
NAME : CMOORE	:RPULSIFAR : ta	: AHS LAY YET	RBARRETT	
DATE : 2/1/91	:3 /14/91	: 3/14/91	: 3 // 4/91	

OFFICIAL RECORD COPY

Document Name: KOVACH 68522/23/25/16

Mr. Thomas J. Kovach Commonwealth Edison Company

Byron/Braidwood Power Stations

CC:

Mr. Gabe Toth
Westinghouse Electric Corporation
Energy Systems Business Unit
Post Office Box 355, Bay 236 West
Pittsburgh, Pennsylvania 15230

Joseph Gallo, Esq. Hopkins and Sutter 888 16th Street, N.W. Suite 700 Washington, D.C. 20006

Regional Administrator U. S. NRC, Region III 799 Roosevelt Road, Bldg. #4 Glen Ellyn, Illinois 60137

Ms. Bridget Little Rorem Appleseed Coordinator 117 North Linden Street Essex, Illinois 60935

Mr. Edward R. Crass
Nuclear Safeguards and Licensing
Division
Sargent & Lundy Engineers
55 East Nonroe Street
Chicago, Illinois 60603

U. S. Nuclear Regulatory Commission Resident Inspectors Office RR#1, Box 79 Braceville, Illinois 60407

Mr. Thomas W. Ortciger, Director Illinois Emergency Services and Disaster Agency 110 East Adams Street Springfield, Illinois 62706

Robert Neumann Office of Public Counsel State of Illinois Center 100 W. Randolph Suite 11-300 Chicago, Illinois 60601 U. S. Nuclear Regulatory Commission Byron/Resident Inspectors Office 4448 North German Church Road Byron, Illinois 61010

Ms. Lorraine Creek Rt. 1, Box 182 Manteno, 111inois 60950

Mrs. Phillip B. Johnson 1907 Stratford Lane Rockford, 111inois 61107

Couglass Cassel, Esq. 17 East Monroe Street Suite 212 Chicago, Illinois 60603

David C. Thomas, Esq. 77 S. Wacker Drive Chicago, Illinois 60601

Michael Miller, Esq. Sidley and Austin One First National Plaza Chicago, Illinois 60690

George L. Edgar Newman & Holtzinger, P.C. 1615 L Street, N.W. Washington, D.C. 20036

Commonwealth Edison Company Byron Station Manager 4450 North German Church Road Byron, Illinois 61010

Illinois Department of Nuclear Safety Office of Nuclear Facility Safety 1035 Outer Park Drive Springfield, Illinois 62704

Commonwealth Edison Company Braidwood Station Manager Rt. 1, Box 34 Braceville, Illinois 60407