MRC FORM 366 (12-61)	LICENSEE EVENT REPORT	APPROVED BY OMB 3150-0011 EXPIRES 4-30-82
CONTROL BLOCK:	(PLEASE PRINT OR TYPE ALL	REQUIRED INFORMATION)
O 1 P A S E S 1 2 0	0 - 0 0 0 0 - 0 0 3 4 1 LICENSE NUMBER 25 25 LICE	1   1   4       57 CAT 58
CON'T  O 1 SOURCE L 6 0 5 0	0 0 3 8 7 7 1 2 1 5 8 2 8 KET NUMBER 48 49 EVENT DATE 74	0 1 1 4 8 3 9
EVENT DESCRIPTION AND PROBABLE	0	
	st Program, a routine, scheduled pre	
0 3 activity was performed	d on the "C" diesel generator. The	diesel was then tested
0 4 and failed. There wer	re no adverse consequences due to th	e fact that this trip is
0 5 present in the trip c	ircuitry only during test runs. In	emergency starts of
0 6 the diesel, this circu	uitry is bypassed.	
0 7		
0 8		
SYSTEM CAUSE CODE CODE		
0 9 E E 11 E	1 A 3 I N S T R U 4 E	Z 15 Z 16
17 LER/AG EVENT YEAR 8 2	SEQUENTIAL OCCURRENCE REPORT NO.	
	AUTDOWN AETHOD HOURS 22 ATTACHMENT NPRD-4 SUBMITTED FORM SUB.  Z 21 0 0 0 0 N 23 N 2 37 40 41 42	PRIME COMP. COMPONENT 26
CAUSE DESCRIPTION AND CORRECT	on a jacket water temperature switc	sh had come loose in
A competature element		
	g bench calibration, the device woul	
	process pressure would disturb the	
1 3 maintenance testing of	f the diesel was successful followin	g the recalibration.
1 4 2		80
	/a   B   31   post-maintena	ince testing
7 8 9 10 12 13 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF	44 45 46	N OF RELEASE (36)
1 6 Z 33 Z 34 n/a	n/a	***
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION	on 39	
1 7 0 0 0 37 Z 38 n/a		80
PERSONNEL INJURIES NUMBER DESCRIPTION (41)		
1 9 7 (42)		80
PUBLICITY	8301260313 830114	NRC USE ONLY
2 0 N 44 n/a	PDR ADOCK 05000387	49 49 40 AC
NAME OF PREPARER	L.A. Kuczynski PHONE	(717) 542-2181 X240