



J. DOUGLAS BIRD
President

1233 East Second
Casper, Wyoming 82601
(307) 677-7201

27 March 1991

Regional Administrator
United States Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Reply to a Notice of Violation
Materials License #49-00152-02

Dear Sir:

07003496

Pursuant to the provisions of 10 CFR 2.201, Wyoming Medical Center is submitting this statement and explanation re to the corrective measures that have been taken to bring this facility into full compliance with its Materials License.

As the records show, there were four Level IV violations, each of which will be addressed as follows:

A. 10 CFR 20.101 (a). Assignment of radiation exposure levels to individuals having lost or misplaced film badges.

REASON FOR VIOLATION: R.S.O. being unfamiliar with this regulation and documentation was not being done when badges were lost.

CORRECTIVE ACTION: Each employee and physician who wears a ring or film badge has been instructed to be extremely careful to avoid losing or misplacing them. If a badge is lost, the R.S.O. will review the individuals previous radiation exposure history and document an estimated value on the exposure records and this value will be reported to Landauer, Inc.

CORRECTIVE STEPS TO AVOID FUTURE VIOLATIONS: The R.S.O. has been instructed to meet regularly with the contract Medical Physicist of Wyoming Medical Center to stay current on NRC regulations and avoid misunderstandings.

Full compliance has been attained as of 6 March 1991. (Departmental meeting held this date).

9104030247 910327
REG4 LIC30
49-00152-02 PDR

Partner - VHA/Mtn. States
affiliate of the Voluntary Hospitals of America System

JE07 11

