



**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

February 1, 1983

Operating License: DPR-58  
Docket No.: 50-315

Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Keppler:

This is to confirm a telephone call made at 1300 hours on February 1, 1983, to Mr. E.R. Swanson, NRC Region III, Resident Inspector in accordance with Technical Specification 6.9.1.8.

At that time Mr. Swanson was informed that the outlet valve of the Unit One Spray Additive Tank was discovered to be in the closed position. The discovery was made at 0915 hours on February 1, 1983, which was approximately seven hours following a surveillance test which required that the valve be placed in the closed position. Upon discovery, the valve was immediately opened.

A follow up report will be submitted within the next fourteen days in accordance with Technical Specification 6.9.1.8.

Sincerely,

for W.G. Smith, Jr.  
Plant Manager

/skf

cc: J.E. Dolan  
R.S. Hunter  
M.P. Alexich  
R.F. Kroeger  
B. Germano  
E. Swanson/N. DuBry RO:III  
R.C. Callen MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
R.O. Bruggee EPRI  
INPO  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (40 copies)  
Dir., MTPC (4 copies)

FEB 4 1983