

MAR 29 1991

Docket No. 50-461

Illinois Power Company
ATTN: J. S. Perry
Vice President
Clinton Power Station
Mail Code V-275
P. O. Box 678
Clinton, IL 61727

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. M. P. Huber and J. F. Smit. of this office on February 25 through March 14, 1991, of activities at Clinton Power Station, Unit 1, authorized by NRC Operating License No. NPF-62 and to the discussion of our findings with Mr. R. Phares and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. The inspection covered the implementation of the Inservice Testing Program. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by Mark A. Ring

M. A. Ring, Chief
Engineering Branch

Enclosure: Inspection Report
No. 50-461/91005(DRS)

See Attached Distribution

RIII	RIII	RIII	RIII	RIII
Huber/lc	[SEE PREVIOUS PAGE FOR CONCURRENCE Smith	Lanksbury	Danielson	Ring
3/ /91	3/ /91	3/ /91	3/ /91	3/29/91

IEOI

MAR 29 1991

Docket No. 50-461

Illinois Power Company
ATTN: J. S. Perry
Vice President
Clinton Power Station
Mail Code V-275
P. O. Box 678
Clinton, IL 61727

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. M. P. Huber and J. F. Smith of this office on February 25 through March 14, 1991, of activities at Clinton Power Station, Unit 1, authorized by NRC Operating License No. NPF-62 and to the discussion of our findings with Mr. R. Ferris and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. The inspection covered the implementation of the Inservice Testing Program. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by Mark A. Ring

M. A. Ring, Chief
Engineering Branch

Enclosure: Inspection Report
No. 50-461/91005(DRS)

See Attached Distribution

RIII <i>LSH</i> for Huber/lc 3/15/91	RIII <i>LSH</i> for Smith 3/15/91	RIII <i>LSH</i> Lanksbury 3/15/91	RIII <i>LSH</i> Danielson 3/15/91	RIII <i>MR</i> Ring 3/29/91
---	--	--	--	--------------------------------------

Distribution

cc w/enclosure:

J. Cook, Manager,

Clinton Power Station

F. Spangenberg, III, Manager -

Licensing and Safety

DCD/DCB (RIDS)

OC/LFDCB

Resident Inspector, RIII

LPM, NRR

J. McCaffrey, Chief, Public

Utilities Division

Patricia O'Brien, Governor's

Office of Consumer Services

S. Zabel, Esquire, Schiff, Hardin,

& Waite

L. Larson, Project Manager,

General Electric Company

Chairman, DeWitt County Board

Illinois Department of

Nuclear Safety

Robert Newmann, Asst. Director

State of Illinois

Perry, SRI