

MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205 February 3, 1983

JAMES P. McGAUGHY, JR. ASSISTANT VICE PRESIDENT

Office of Inspection & Inforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station

Unit 1

Docket No. 50-416 License No. NPF-13 File 0260/L-835.0

Smoke Detection Zone Alarmed

and Would Not Reset LER 82-183/99 X-0

AECM-83/76

On December 22, 1982, the smoke detection zone covering the Auxiliary Building corridor area (elevation 139 feet) alarmed and would not reset. A fire watch was established pursuant to Technical Specification 3.3.7.9. Attached is Special Report LER 82-183/99 X-0.

Yours truly,

JPM:sap Attachment

cc: Mr. N. L. Stampley (w/a)

Mr. R. B. McGehee (w/o)

Mr. T. B. Conner (w/o)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555

8302140053 830203 PDR ADOCK 05000416 PDR

Te 22