

February 18, 1983

Docket No. 50-315
Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering
2 Broadway
New York, NY 10004

Gentlemen:

Thank you for your letter dated January 10, 1983, informing us of the steps you have taken to correct the noncompliance which we brought to your attention in Inspection Report Nos. 50-315/82-15 and 50-316/82-15 forwarded by our letter dated December 10, 1982. On February 10, 1983, additional information concerning the first item of noncompliance was obtained during conversation between Mr. W. G. Smith, Jr., D. C. Cook Plant Manager and Mr. E. R. Swanson of our office. We understand that you have taken steps to improve communications between AEPSC and the plant on licensing issues. We are also aware that a procedure is being prepared to ensure proper implementation of technical specification changes. We will examine these matters during a subsequent inspection.

Your cooperation with us is appreciated.

Sincerely,

~~Original~~ Signed by C.E. Norelius"

8302250306 830218
PDR ADOCK 05000315
G PDR

C. E. Norelius, Director
Division of Project and
Resident Programs

cc: W. G. Smith, Jr., Plant
Manager

cc w/ltr dtd 1/10/83:
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office

IE01

OFFICE	RIII	RIII	RIII	RIII			
SURNAME	Holzmet/rl	Boyd	Streeter	Norelius			
DATE	2/16/83	2-16-83	2/16/83	2/17/83			