

February 17, 1983

DJS Ltr. #83-171

James G. Keppler, Regional Administrator Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Reportable Occurrence Peport #83-05/01T-0, Docket #050-249 is being substitud to your office in accordance with Dresden Nuclear Power Station Technical specification 6.6.B.1.(b), operation of the unit or affected systems when any parameter or operation subject to a limiting condition is less conservative than the least conservative aspect of the limiting condition for operation established in the technical specifications.

D. J. Scott

Station Superintendent Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC