

CONTROL BLOCK: 1 2 3 4 5 6 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M S G G S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1

REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 0 1 2 8 8 3 8 0 2 2 4 8 3 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 On January 28, 1983, fire doors 1A401, 1A202, and 1A108 (Auxiliary Building) were

0 3 blocked open to allow the routing of electrical cords and air hoses for planned

0 4 maintenance activities conducted in the areas secured by these fire doors. This

0 5 required operating under the action statements of T.S.3.7.7. The event had no effect

0 6 on the health and safety of the public and did not constitute a threat to plant

0 7 safety. This is reported pursuant to T.S.6.9.1.13.b.

0 8

7 8 9

0 9

7 8

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 14 VALVE SUBCODE 15

0 11 A B 12 X 13 Z Z Z Z Z Z 14 Z 15 Z 16 Z

17 LER/RO REPORT NUMBER 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 26 27 28 OCCURRENCE CODE 29 30 REPORT TYPE 31 32 REVISION NO.

0 18 X 19 Z 20 Z 21 Z 22 0 0 0 0 23 N 24 N 25 Z 26 Z 9 9 9

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The doors were blocked open to perform planned maintenance. An hourly fire watch

1 1 was conducted in accordance with T.S.3.7.7.a. The subject fire doors were locked

1 2 and the alarms activated within 7 days. This is a final report.

1 3

1 4

7 8 9

1 5

7 8 9

FACILITY STATUS 10 % POWER 11 OTHER STATUS 12 METHOD OF DISCOVERY 13 DISCOVERY DESCRIPTION 14

1 6 G 28 0 0 0 29 NA A 31 Planned Maintenance 32

10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONTENT 33 RELEASED OF RELEASE 34 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

1 7 Z 33 Z 34 NA NA

10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL EXPOSURES 37 NUMBER 38 TYPE 39 DESCRIPTION 40

1 8 0 0 0 37 Z 38 NA

10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL INJURIES 40 NUMBER 41 DESCRIPTION 42

1 9 0 0 0 40 NA

10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LOSS OF OR DAMAGE TO FACILITY 43 TYPE 44 DESCRIPTION 45

1 9 Z 42 NA

10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PUBLICITY 45 ISSUED 46 DESCRIPTION 47

2 0 N 44

10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

8303010233 830224
PDR ADOCK 05000416
S PDR

68 69 70 71 72 73 74 75 76 77 78 79 80

NRC USE ONLY