

APPENDIX A
NOTICE OF VIOLATION

Georgia Power Company
Hatch

Docket No. 50-321
License No. DPR-57

As a result of the inspection conducted on December 13-16, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification 6.8.2, as implemented by plant procedure HNP-9, "Procedure Writing, Use and Control," requires approval, issue and control of procedures, and procedure revisions in accordance with plant procedure HNP-9.

Contrary to the above, procedure changes were not approved, issued and controlled in accordance with plant procedure HNP-9 in that on December 14, 1982, an unapproved, uncontrolled change to plant procedure HNP-6914 was being used for qualification of class 1 pipe welders.

This is a Severity Level V Violation (Supplement I.F).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: JAN 03 1983