

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: C I A R S S 1 2 0 0 - 0 0 0 0 0 - 0 0 0 4 1 1 1 1 4 5  
LICENSE NUMBER: 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40  
REPORT SOURCE: L 6 0 5 0 0 0 3 1 2 0 2 0 4 8 2 3 0 3 0 2 8 3 9  
DOCKET NUMBER: 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70  
EVENT DATE: 71 72 73 74 75 76 77 78 79 80  
REPORT DATE: 81 82 83 84 85 86 87 88 89 90

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
On February 4, 1983, the "C" RCP was manually tripped due to excessive vibration. The RPS "D" Channel Underpower Relay did not sense the trip of the "C" RCP. This resulted in an improper lineup of the logic for the AFW P-318 Autostart. There were no effects on plant or public safety since Channel B was available to provide AFW autostart.

SYSTEM CODE: I A 11 CAUSE CODE: E 12 CAUSE SUBCODE: A 13 COMPONENT CODE: R E L I A Y X 14 COMP SUBCODE: A 15 VALVE SUBCODE: Z 16  
EVENT YEAR: 8 3 21 22 SEQUENTIAL REPORT NO.: 0 0 7 23 24 OCCURRENCE CODE: 0 3 25 26 REPORT TYPE: L 27 28 REVISION NO.: 0 29 30  
LER/RO REPORT NUMBER: 17 18 ACTION TAKEN: X 19 FUTURE ACTION: 20 EFFECT ON PLANT: Z 21 SHUTDOWN METHOD: 22 HOURS: 0 0 0 23 24 ATTACHMENT SUBMITTED: Y 25 26 NPD-4 FORM SUB: Y 27 28 PRIME COMP SUPPLIER: N 29 30 COMPONENT MANUFACTURER: W 2 0 9 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
The "D" RPS Channel Underpower relay did not sense the "C" RCP trip. Power to this relay was removed to de-energize it, thus placing the RPS Channel D into the proper logic. The cause will be investigated during the current outage and be reported in a followup.

FACILITY STATUS: H 28 % POWER: 0 0 0 29 OTHER STATUS: N/A 30 METHOD OF DISCOVERY: A 31 DISCOVERY DESCRIPTION: Investigation by I&C Techs. 32  
ACTIVITY CONTENT: Z 33 Z 34 AMOUNT OF ACTIVITY: N/A 35 LOCATION OF RELEASE: N/A 36  
PERSONNEL EXPOSURES: 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PERSONNEL INJURIES: 40 41 42 43 44 45 46 47 48 49 50  
LOSS OF OR DAMAGE TO FACILITY: 43 44 45 46 47 48 49 50  
PUBLICATION: Y 44 45 46 47 48 49 50  
ISSUED DESCRIPTION: Local newspapers and wire services. 45 46 47 48 49 50

NAME OF PREPARER: R. W. Colombo PHONE: (916) 452-3211