

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

W. L. STEWART  
VICE PRESIDENT  
NUCLEAR OPERATIONS

May 19, 1983

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
Attn: Mr. Robert A. Clark, Chief  
Operating Reactors Branch No. 3  
Division of Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Serial No. 292  
NO/JHL:cfm  
Docket No. 50-339  
License No. NPF-7

Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY  
NORTH ANNA POWER STATION UNIT NO. 2  
DIESEL GENERATOR RELIABILITY

With regard to diesel generator reliability, North Anna 2 License Condition 2.C(15)(h)(2) states, "The lube oil system shall be modified to the manufacturer's recommendations for providing continuous lubrication of the lower portions of the engine. The modifications shall further provide for partial filling of the upper lube oil supply header and a lube oil booster/accumulator system which will force oil into the upper lube oil header during engine startup. The modifications shall be completed no later than the second refueling outage."

In addition, North Anna 2 License Condition 2.C(15)(h)(4) states, "The fuel oil storage and transfer system shall be modified to include the installation of a separate high level alarm for each day tank, the installation of independent pressure switches for each pump which will be set to stop the pumps on high day tank level, and the submittal of Technical Specifications verifying proper operation of all transfer pump control switches and day tank high level alarms. Non-qualified pressure switches will be installed by October 31, 1982. These switches are being qualified by the manufacturer. Should these switches fail qualification tests, the non-qualified switches shall be replaced with qualified units. The modifications shall be completed no later than the second refueling outage."

North Anna Unit 2 is completing its second refueling outage. Diesel generator reliability modifications to the lube oil system have been completed. This satisfies North Anna 2 License Condition 2.C(15)(h)(2). Modifications to the fuel oil storage and transfer system have been completed. High level alarms for each day tank have been installed and qualified independent pressure switches for each pump have been installed. The submittal of Technical Specifications to verify proper operation of all transfer pump control


8305270150 830519  
PDR ADDCK 05000339  
P PDR

A001  
5  
1/0

VIRGINIA ELECTRIC AND POWER COMPANY TO Harold R. Denton

switches and day tank high level alarms is not required. The definition of OPERABLE - OPERABILITY, in Section 1.0 of the North Anna Unit 2 Technical Specifications, shall apply. Periodic test procedures will include that diesel generator transfer pump control switches and day tank high level alarms are monitored for operability on a staggered test basis. This satisfies North Anna Unit 2 License Condition 2.C(15)(h)(4).

Very truly yours,

  
W. L. Stewart

cc: Mr. James P. O'Reilly  
Regional Administrator  
Region II

Mr. M. B. Shymlock  
NRC Resident Inspector  
North Anna Power Station