

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 20, 1982

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/82-56. This report concerns T.S.6.9.1.12(i), "Performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than assumed in the accident analyses in the safety analysis report or technical specifications bases; or discovery during unit life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition". This incident was considered to be of no significance with respect to the health and safety of the public.

Note that while the enclosed LER form indicates that an attachment to the form is being submitted (Item No. 23), no attachment is enclosed. Instead, Mr. W. O. Parker, Jr.'s (DPC) letters to Mr. H. R. Denton (NRC/ONRR) of July 13 and 14, 1982 are to be considered the attached detailed report for this LER. The July 13 letter details the examinations and evaluations performed by Duke Power Company and Westinghouse Electric Corporation with regards to this event, and provides the conclusions. The July 14 letter details interim actions to continue until the affected thermal sleeves are removed which Duke Power Company agreed to during discussions with the NRC staff on July 14, 1982.

Very truly yours,


William O. Parker, Jr.

PBN/jfw
Attachment

OFFICIAL COPY

8208020075 820720
PDR ADOCK 05000369
S PDR

IF22

82 JUL 26 10:30

James P. O'Reilly
July 20, 1982
Page 2

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. P. R. Bemis
Senior Resident Inspector
McGuire Nuclear Station

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339