

APPENDIX A

NOTICE OF VIOLATION

Duke Power Company
Oconee 1

Docket No. 50-269
License No. DPR-38

As a result of the inspection conducted on January 11 - February 10, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification 6.4.1.g., requires that the station be operated and maintained in accordance with approved Radiation Control Procedures. Station Directive 3.8.2.3, "Health Physics High Radiation Door Tour" 12/6/79, Section 1.1, states all high radiation area doors are securely locked or guarded at all times except for entry and exit.

Contrary to the above, all high radiation area doors were not locked in that on January 18, 1983, an entrance to the HPI/LPI pump room hatch area, a high radiation area, was discovered unsecured with no positive control over entry.

This is a Severity Level V Violation (Supplement E.2.).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: MAR 07 1983

8305270636 830425
PDR ADDCK 05000269
PDR
Q