



Commonwealth Edison
LaSalle County Nuclear Station
Rural Route #1, Box 220
Marseilles, Illinois 61341
Telephone 815/357-6761

50-373

September 10, 1982

James G. Keppler
Regional Administrator
Director of Regulatory Operations - Region 111
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Sir:

In accordance with LaSalle County Station Unit 1 Facility Operating License NPF-11, Appendix B, Section 3.2, we are submitting to you a copy of the NPDES noncompliances for LaSalle County Nuclear Generating Station Permit No. 1L0048151.

G. J. Diederich
Superintendent
LaSalle County Station

FRL

GJD/FRL/JGW/jfe

Enclosure

cc: DVR Report

8209270126 820910
PDR ADOCK 05000373
S PDR

SEP 22 1982

PE22



Commonwealth Edison
LaSalle County Nuclear Station
Rural Route #1, Box 220
Marseilles, Illinois 61341
Telephone 815/357-6761

September 10, 1982

U. S. Environmental Protection Agency
Region V, Enforcement Division
ATTN: Chief, Compliance Unit
230 South Dearborn Street
Chicago, Illinois 60604

Illinois Environmental Protection Agency
Division of Water Pollution Control
Compliance Management Unit
2200 Churchill Road
Springfield, Illinois

SUBJECT: NPDES Noncompliances For LaSalle County Nuclear Generating
Station - Permit No. 1L0048151

Dear Sir:

In accordance with Standard Condition 12, we wish to submit the following notice of noncompliances, which are listed chronologically in the attached table.

If there are any questions, please contact Joe Williams of my staff at (815)-357-6761, extension 201.

G. J. Diederich
G. J. Diederich
Superintendent
LaSalle County Station

^{FRL}
GJD/FRL/JGW/jfe

cc: Director of Water Quality, Environmental Affairs Manager,
Nuclear Stations Division

LASALLE COUNTY NUCLEAR GENERATING STATION
N.P.D.E.S. PERMIT NO: IL0048151
NONCOMPLIANCE REPORT

DISCHARGE NUMBER AND DESCRIPTION: 001c Low Volume Waste Radwaste Discharge Tanks

PARAMETER AND PERMIT LIMIT: Total suspended solids - 15 mg/l
Total Iron - 1.0 mg/l
NONCOMPLIANCE, DATE, AND DURATION: Total Copper- 1.0 mg/l

No sampling and analysis Aug. 16 - Aug. 22, 1982, not applicable

CAUSE OF NONCOMPLIANCE:

The composite sampler cannot operate automatically. The operator did not inform the Chemistry Technician that the discharge was taking place until after it had been initiated. In another case the operator failed to inform the Technician that the discharge had been secured.

CORRECTIVE ACTION:

The Operating Department has been informed to notify the Rad/Chem Technician prior to initiating the discharge, and prior to securing the discharge. In addition a work request has been initiated to automatically start and stop the composite sampler.

DATE RECOGNIZED AS A VIOLATION:

August 22, 1982

DATE INVESTIGATED:

August 25, 1982