

OCT 27 1982

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Richard P. Crouse
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the routine safeguards inspection conducted by Messrs. A. G. Finley and T. J. Madeda of this office on October 12-15, 1982, of activities at Davis-Besse Nuclear Power Station authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. S. M. Quennoz, Assistant Station Superintendent, and other members of his staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

Areas examined during the inspection concern a subject matter which is exempt from disclosure according to Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Consequently, our report of this inspection will not be placed in the Public Document Room.

ATTACHMENT CONTAINS
Part 2.790(d) Information

DMB:
IE 02

8211020167 821027
PDR ADOCK 05000346
G PDR

Toledo Edison Company

2

OCT 27 1982

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by J. R. Miller

J. R. Miller, Chief
Technical Inspection Branch

Enclosure: Inspection Report
No. 50-346/82-28(DETP)
(Part 2.790(d) Information)

cc w/encl:
T. D. Murray, Station
Superintendent
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII

cc w/encl, w/o Part 2.790(d)
Information:
Harold W. Kohn, Power Siting
Commission
Helen W. Evans, State of Ohio
Robert M. Quillin, Ohio
Department of Health

RIII *sv*
Finley/sv
10/26/82

RIII
for
Creed

RIII
Reyes
10/27/82

RIII
Miller

ATTACHMENT CONTAINS
Part 2.790(d) Information