

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-346/82-28(DETP)

Docket No. 50-346

License No. NPF-3

Safeguard Group IV

Licensee: Toledo Edison Company  
Edison Plaza  
300 Madison Avenue  
Toledo, OH 43652

Facility Name: Davis-Besse Nuclear Power Station

Inspection At: Davis-Besse, Oak Harbor, OH

Inspection Conducted: October 12-15, 1982

Date of Last Material Control and Accounting Inspection: July 20-23, 1980

Type of Inspection: Unannounced Material Control and Accounting

Inspectors: A. G. Finley  
A. G. Finley, Auditor

10/26/82  
Date

T. J. Madeda  
T. J. Madeda, Physical  
Protection Specialist

10/26/82  
Date

Approved By: J. R. Creed  
for J. R. Creed, Chief  
Safeguards Section

10/26/82  
Date

Inspection Summary

Inspection on October 12-15, 1982 (Report No. 50-346/82-28(DETP))

Areas Inspected: Facility Organization and Operation, Measurements and Control, Inventory, Shipping and Receiving, Internal Controls, Records and Reports, and Management of Material Control System. The inspection involved 44 inspection-hours onsite by two NRC inspectors and was begun during the regular hours.

Results: The licensee was found to be in compliance with NRC requirements in the seven areas examined during the inspection.

(Details - Part 2.790(d) Information)

8211020177 821027  
PDR ADOCK 05000346  
Q PDR