



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

May 31, 1983

Mr. J.M. Allan
Acting Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 83-076/01P-0
ER 100450 FILE 841-23
PLA-1694

Docket No. 50-387
License No. NPF-14

Dear Mr. Allan:

This transmission confirms the report of May 27, 1983, by A.P. Piemontese to J. McCann of your staff, in that a walkdown of the Control Room Emergency Outside Air Supply System (CREOASS) revealed cables run through an open door. The cables have been removed and the door closed.

This condition is considered reportable in accordance with Technical Specification 6.9.1.8.f, and additional information regarding circumstances of the incident and corrective actions to be taken will be provided in the fourteen day follow-up report.

H.W. Keiser
Superintendent of Plant - Susquehanna

APP/pjg

cc: G.G. Rhoads
Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE29
No