



January 14, 1983

Log No. K83-080  
File: RR 2 (NP-33-82-84)

Docket No. 50-346  
License No. NPF-3

Mr. James G. Keppler  
Regional Administrator, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

LER No. 82-067  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: December 17, 1982

Enclosed are three copies of Licensee Event Report 82-067 which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

A handwritten signature in cursive script that reads 'Terry D. Murray'.

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosures

cc: Mr. Richard DeYoung, Director  
Office of Inspection and Enforcement  
Encl: 30 copies

Mr. Norman Haller, Director  
Office of Management and Program Analysis  
Encl: 3 copies

Mr. Tom Peebles  
NRC Resident Inspector  
Encl: 1 copy

8301240104 830114  
PDR ADOCK 05000346  
S PDR