

DMB 016

JUNE 1 1983

DISTRIBUTION
Docket File

Docket No. 50-346

Mr. Richard P. Crouse
Vice President, Nuclear
Toledo Edison Company
Chairman, B&W Owners Group
Executive Committee
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

- BSheron
- WJohnston
- CBerlinger
- FRosa
- CHeltemes
- KKniel
- ~~Gray File~~
- EJordan
- JTaylor
- ACRS-10
- PKadambi
- RIngram
- Gray File
- EBlackwood
- Hornstein
- BDLiaw
- DZiemann

(with incoming mat'l)

Dear Mr. Crouse:

We have recently been made aware of the organizational structure which has been established by the B&W Owners Group to deal with generic regulatory issues. Consistent with our previous discussion, NRR has identified individual contacts at the Branch Chief level or higher as shown in Attachment 1 for each of the sub-committees operating under the Owners Group Steering Committee. These contacts are for the technical interaction between the sub-committees and the staff. I have designated Mr. Gus Lainas, Assistant Director for Operating Reactors, as the licensing contact with overall responsibility to coordinate and manage the staff's interactions.

Sincerely,

Original Signed by
H. R. Denton

Harold R. Denton, Director
Office of Nuclear Reactor Regulation

Attachment:
As Stated

cc w/attachment:
See next page

8306220215 830601
PDR ADOCK 05000346
PDR

*See previous white for concurrences.

D:AEOD
CHeltemes
5/1/83

D:DHFS *
HThompson
5/1/83

D:DST
TSpeis*
5/23/83

OFFICE	ORB#4:DL	C-ORB#4:DL	AD:OR:DL	D:Dr	DANRR	D:DE	D:DSI
SURNAME	PKadambi;cf	JStolz*	GLainas*	DEisenhut	HDenton	RVollmer*	RMattson*
DATE	5/3/83	5/19/83	5/19/83	5/3/83	6/1/83	5/20/83	5/23/83

Docket No. 50-346

DISTRIBUTION
Docket File
NRC PDR
L PDR
ORB#4 Rdg
DEisenhut
OELD
NSIC
EJordan
JTaylor
ACRS-10
PKadambi
RIngram
Gray File
EBlackwood
Hornstein

Mr. Richard P. Crouse
Vice President, Nuclear
Toledo Edison Company
Chairman, B&W Owners Group
Executive Committee
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

Dear Mr. Crouse:

We have recently been made aware of the organizational structure which has been established by the B&W Owners Group to deal with the generic regulatory issues. Consistent with our previous discussion, NRR has identified individual contacts at the Branch Chief level or higher as shown in Attachment 1 for each of the sub-committees operating under the Owners Group Steering Committee. These contacts are for the technical interaction between the sub-committees and the staff. The Division of Licensing has identified Dr. N. Prasad Kadambi as the licensing contact with responsibility to manage the staff's evaluation of all the issues.

Sincerely,

Harold R. Denton, Director
Office of Nuclear Reactor Regulation

Attachment:
As Stated

cc w/attachment:
See next page

*See previous white for concurrences.

887
DD:DHFS
DZiemann
5/26/83
D:DST
TSpeis*
5/23/83

OFFICE	ORB#4:DL	C-ORB#4:DL	AD:OR:DL	D:DL	D/NRR	D:DE	D:DSI
SURNAME	*PKadambi;cf	JStolz *	GLainas*	DEisenhut	HDenton	RVollmer *	RMattson*
DATE	5/ /83	5/ /83	5/ /83	5/27/83	5/ /83	5/ /83	5/ /83

Docket No. 50-346

Mr. Richard P. Crouse
Vice President, Nuclear
Toledo Edison Company
Chairman, B&W Owners Group
Executive Committee
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

DISTRIBUTION

Docket File	BDLiaw
NRC PDR	DZiemann
L PDR	BSheron
ORB#4 Rdg	WJohnston
DEisenhut	CBerlinger
OELD	FRosa
NSIC	CHeltemes
EJordan	KKniel
JTaylor	
ACRS-10	
PKadambi	
RIngram	
Gray File	
EBlackwood	
HOrnstein	

Dear Mr. Crouse:

We have recently been made aware of the organizational structure which has been established by the B&W Owners Group to deal with the generic regulatory issues. Consistent with our previous discussion, NRR has identified individual contacts at the Branch Chief level or higher as shown in Attachment 1 for each of the sub-committees operating under the Owners Group Steering Committee. These contacts are for the technical interaction between the sub-committees and the staff. The Division of Licensing has identified Dr. N. Prasad Kadambi as the licensing contact with responsibility to manage the staff's evaluation of all the issues.

Sincerely,

Harold R. Denton, Director
Office of Nuclear Reactor Regulation

Attachment:
As Stated

cc w/attachment:
See next page

D:AEOD	D:DHFS	<i>Full activity</i>
CHeltemes	HThompson	D:DST
5/ /83	5/ /83	TSpeis
		5/23/83

OFFICE ▶	ORB#4:DL	C-ORB#4:DL	AD:OR:DL	D:DL	D/NRR	D:DE	D:DSI
SURNAME ▶	PKadambi;cf	JStoltz	GLaThas	DEisenhut	HDenton	RKellmer	RMattson
DATE ▶	5/19/83	5/19/83	5/19/83	5/ /83	5/ /83	5/20/83	5/23/83

Toledo Edison Company

cc w/enclosure(s):

Mr. Donald H. Hauser, Esq.
The Cleveland Electric
Illuminating Company
P. O. Box 5000
Cleveland, Ohio 44101

Gerald Charnoff, Esq.
Shaw, Pittman, Potts
and Trowbridge
1800 M Street, N.W.
Washington, D. C. 20036

Paul M. Smart, Esq.
Fuller & Henry
300 Madison Avenue
P. O. Box 2088
Toledo, Ohio 43603

Mr. Robert B. Borsum
Babcock & Wilcox
Nuclear Power Generation Division
7910 Woodmont Avenue, Suite 220
Bethesda, Maryland 20814

President, Board of County
Commissioners of Ottawa County
Port Clinton, Ohio 43452

Attorney General
Department of Attorney General
30 East Broad Street
Columbus, Ohio 43215

Harold Kahn, Staff Scientist
Power Siting Commission
361 East Broad Street
Columbus, Ohio 43216

Mr. James G. Keppler, Regional Administrator
U. S. Nuclear Regulatory Commission, Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Mr. Larry D. Young
Manager, Nuclear Licensing
Toledo Edison Company
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

U.S. Nuclear Regulatory Commission
Resident Inspector's Office
5503 N. State Route 2
Oak Harbor, Ohio 43449

Regional Radiation Representative
EPA Region V
230 South Dearborn Street
Chicago, Illinois 60604

Ohio Department of Health
ATTN: Radiological Health
Program Director
P. O. Box 118
Columbus, Ohio 43216

James W. Harris, Director (Addressee Only)
Division of Power Generation
Ohio Department of Industrial Relations
2323 West 5th Avenue
P. O. Box 825
Columbus, Ohio 43216

ATTACHMENT 1

IDENTIFICATION OF TECHNICAL CONTACTS FOR B&W GENERIC ISSUES

B&W Owner's Group Subcommittee	NRR Contact	
	Name	Designation
1. NDE	B. D. Liaw	Branch Chief, MTEB
2. Operator Support	D. L. Ziemann	Acting Deputy Director, DHFS
3. ATWS	B. Sheron	Branch Chief, RSB
4. Steam Generator	W. Johnston	Assistant Director, MCET
5. Core Performance	C. Berlinger	Branch Chief, CPB
6. Analysis	B. Sheron	Branch Chief, RSB
7. RG 1.97	F. Rosa	Branch Chief, ICSB
8. Transient Assessment Program	A. Thadani	Branch Chief, RRAB
9. Materials	B. D. Liaw	Branch Chief, MTEB
10. Availability	Not Applicable	
11. Materials Procurement	Not Applicable	
12. PTS	K. Kniel	Branch Chief, GIB