

NSNRC REGION II  
ATLANTA, GEORGIA

83 MAR 10 A 9: 23



March 7, 1983  
L-83-125

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: St. Lucie Unit 1  
Docket No. 50-335  
IE Bulletin 83-01

We have reviewed IE Bulletin 83-01 [Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal] and have determined that St. Lucie Unit 1 does not have the subject breakers or trip design.

We are evaluating the Bulletin for lessons to be learned at St. Lucie Unit 1.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/PLP/js

cc: Harold F. Reis, Esquire  
PNS-LI-83-159-1

8303210352 830307  
PDR ADOCK 05000335  
PDR


IE31

STATE OF FLORIDA    )  
                          )  
                          )        ss.  
COUNTY OF DADE     )

Robert E. Uhrig, being first duly sworn, deposes and says:

That he is Vice President of Florida Power & Light Company, the Licensee herein;

That he has executed the foregoing document; that the statements made in this said document are true and correct to the best of his knowledge, information, and belief, and that he is authorized to execute the document on behalf of said

  
Robert E. Uhrig

Subscribed and sworn to before me this

7th day of March, 1983

Cheryl I. Fredrick  
NOTARY PUBLIC, in and for the County of Dade,  
State of Florida

Notary Public, State of Florida at Large  
My Commission Expires October 30, 1983  
Bonded thru Meynard Bonding Agency

My commission expires: \_\_\_\_\_