USNRO REGION II ATLANTA GEORGIA

83 JUN 15 P8: 28



June 8, 1983 L-83-353

Mr. James P. O'Reilly Regional Administrator, Region II U. S. Nuclear Regulatory Commission 101 Marietta Street NW, Suite 2900 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: Turkey Point Units 3 & 4

St. Lucie Unit 1

Docket Nos. 50-250, 50-251, 50-335

JE Bulletin 83-03

We have reviewed IE Bulletin 83-03 (Check Valve Failures in Raw Water Cooling Systems of Diesel Generators) as it applies to Turkey Point Units 3 and 4 and St. Lucie Unit 1, and have reviewed our diesel generator cooling water systems. Our closed cooling radiator systems contain no check valves according to the prints and physical verification and, as such, the Bulletin does not apply.

Should you or your staff have any questions on this information, please contact us.

Very truly yours,

Robert E. Uhrig Vice President

Advanced Systems & Technology

REU/PLP/js

cc: Harold F. Reis, Esquire

US NRC Document Control Desk

6a

SS. COUNTY OF PALM BEACH) Robert E. Uhrig , being first duly sworn, deposes and says: That he is Vice President of Florida Power & Light Company, the Licensee herein; That he has executed the foregoing document; that the statements made in this document are true and correct to the best of his knowledge, information, and belief, and that he is authorized to execute the document on behalf of said

Subscribed and sworn to before me this

STATE OF FLORIDA

Li ansee.

NOTARY PUBLIC, in and for the County of Palm Beach, State of Florida.

Notary Public, State of Floride at Large My Commission Expires October 30, 1983 My commission expires: Bonded thru Maynard Bonding Agency