CONTAINS 2,790 INFORMATION

JUN 22 1983

Westinghouse Electric Corporation ATTN: Mr. W. H. Britton, Manager Columbia Plant Nuclear Fuel Division Drawer R Columbia, SC 29250

Gentlemen:

SUBJECT: REPORT NO. 70-1151/83-10

This refers to the routine safeguards inspection conducted by Mr. B. L. Hall of this office on June 6 - 8, 1983, of activities authorized by NRC License No. SNM-1107 at Westinghouse Nuclear Fuel Division and to the discussions of our findings held with Mr. B. Britton, Plant Manager, at the conclusion of the inspection.

Areas examined during this inspection included your program for safeguarding special nuclear material under the applicable provisions of Title 10, Code of Federal Regulations, Part 73, "Physical Protection of Plants and Materials" and the specific requirements of your approved Security Plan. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, performance tests, and observations by the inspector.

Within the scope of this inspection, no violations or deviations were disclosed.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, activities involving safeguards and security measures are exempt from public disclosure; therefore, the enclosed inspection report with the exception of the report cover page, which is an inspection summary, will not be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

J. Philip Stohr, Director Division of Emergency Preparedness and Materials Safety Programs

TEOR

Enclosure: Inspection Report No. 70-1151/83-10 (Exempt from Disclosure)

8306290433 830622 PDR ADDCK 07001151 C PDR

MATERIAL TRANSMITTED HEREWITH CONTAINS 2.790 INFORMATION MATERIAL TRANSMITTED HEREWITH CONTAINS 2.790 INFORMATION

Westinghouse Electric Corporation

JUN 22 15.83

bcc w/encl: IE/DFFMS/SB NMSS File NMSS/SG Document Management Branch NRC Resident Inspector

.

.

 \mathbf{x}


bcc w/Inspection Summary State of South Carolina

bcc w/o encl: License Fee Management Branch

RID

BHa11:my 06/20/83







JPStonr 06721/83

MATERIAL TRANSMITTED HEREWITH CONTAINS 2.790 INFORMATION