



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT TEXAS 77704


AREA CODE 713 838-6631

June 21, 1983
RBG- 15,278
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Collins:

River Bend station Unit 1
Docket No. 50-458
Interim Report/DR-108



On April 6, 1983, Gulf States Utilities Company (GSU) notified Region IV of a condition potentially reportable under 10CFR50.55(e) concerning pipe support standard components supplied by Bergen-Paterson Pipe Support Corporation that did not conform to those referenced on design drawings (DR-108). GSU is awaiting further information from our architect-engineer. An interim or final status report will be provided by August 10, 1983.

Sincerely,

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

PJR
JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (SRI)

IE 27
1/0