

September 7, 1994

Mr. Donald A. Reid, Vice President  
Operation:  
Vermont Yankee Nuclear Power Corporation  
Ferry Road  
Brattleboro, VT 05301

SUBJECT: VERMONT YANKEE NUCLEAR POWER STATION - RESPONSE TO NRC BULLETIN  
93-02, SUPPLEMENT 1, "DEBRIS PLUGGING OF EMERGENCY CORE COOLING  
SUCTION STRAINERS" (TAC NO. M90183)

Dear Mr. Reid:

This letter acknowledges receipt of your response dated April 19, 1994, to NRC Bulletin 93-02, Supplement 1 (Bulletin). The Bulletin was issued February 18, 1994, for action to all Boiling Water Reactor (BWR) licensees and for information to all Pressurized Water Reactor (PWR) licensees. The purpose of the Bulletin was to inform BWR and PWR licensees about the vulnerability of emergency core cooling system (ECCS) suction strainers in BWRs and containment sumps in PWRs to clogging during the recirculation phase of a loss-of-coolant accident (LOCA). It is requested that BWR licensees take the appropriate actions to ensure reliability of the ECCS in view of the information discussed in this Bulletin supplement, and to require that BWR licensees report to the NRC on the requested actions taken. Your response adequately addressed the actions you will take to assure the operability of ECCS recirculation. We will await your report on completion of the requested actions. Please retain any records of your actions in response to this Bulletin, as subsequent inspection activities may be conducted in regard to this issue.

Should you have any questions, please contact me at (301) 504-1429 or the Lead Project Manager for this issue, John B. Hickman at (301) 504-3017.

Sincerely,

original signed by Ronald Eaton for  
Daniel H. Dorman, Project Manager  
Project Directorate I-3  
Division of Reactor Projects - I/II  
Office of Nuclear Reactor Regulation

Docket No. 50-271

cc: See next page

DISTRIBUTION:

Docket File	SVarga	SLittle	JLinville, RI
PUBLIC	CMiller	DDorman	JHickman
PDI-3 Reading	WButler	OGC	RElliott

DOCUMENT NAME: A:VYM90183.LTR

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	LA:PDI3:DRPE	PM:PDI3:DRPE	BC:SCSB	D:PDI3:DRPE	C
NAME	SLittle	DDorman:mw	RJBarrett	WButler	
DATE	8/30/94	8/30/94	9/14/94	9/17/94	

OFFICIAL RECORD COPY

9409090240 940907  
PDR ADOCK 05000271  
Q PDR

030002

NRC FILE CENTER COPY

DFU/10



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D.C. 20555-0001

September 7, 1994

Mr. Donald A. Reid, Vice President  
Operations  
Vermont Yankee Nuclear Power Corporation  
Ferry Road  
Brattleboro, VT 05301


SUBJECT: VERMONT YANKEE NUCLEAR POWER STATION - RESPONSE TO NRC BULLETIN  
93-02, SUPPLEMENT 1, "DEBRIS PLUGGING OF EMERGENCY CORE COOLING  
SUCTION STRAINERS" (TAC NO. M90183)

Dear Mr. Reid:

This letter acknowledges receipt of your response dated April 19, 1994, to NRC Bulletin 93-02, Supplement 1 (Bulletin). The Bulletin was issued February 18, 1994, for action to all Boiling Water Reactor (BWR) licensees and for information to all Pressurized Water Reactor (PWR) licensees. The purpose of the Bulletin was to inform BWR and PWR licensees about the vulnerability of emergency core cooling system (ECCS) suction strainers in BWRs and containment sumps in PWRs to clogging during the recirculation phase of a loss-of-coolant accident (LOCA). It is requested that BWR licensees take the appropriate actions to ensure reliability of the ECCS in view of the information discussed in this Bulletin supplement, and to require that BWR licensees report to the NRC on the requested actions taken. Your response adequately addressed the actions you will take to assure the operability of ECCS recirculation. We will await your report on completion of the requested actions. Please retain any records of your actions in response to this Bulletin, as subsequent inspection activities may be conducted in regard to this issue.

Should you have any questions, please contact me at (301) 504-1429 or the Lead Project Manager for this issue, John B. Hickman at (301) 504-3017.

Sincerely,

  
Daniel H. Dorman, Project Manager  
Project Directorate I-3  
Division of Reactor Projects - I/II  
Office of Nuclear Reactor Regulation

Docket No. 50-271

cc: See next page

Donald A. Reid, Vice President  
Operations

Vermont Yankee Nuclear Power Station

cc:

Mr. Jay Thayer, Vice President  
Yankee Atomic Electric Company  
580 Main Street  
Bolton, Massachusetts 01740-1398

Regional Administrator, Region I  
U. S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, Pennsylvania 19406

R. K. Gad, III  
Ropes & Gray  
One International Place  
Boston, Massachusetts 02110-2624

Mr. Richard P. Sedano, Commissioner  
Vermont Department of Public Service  
120 State Street, 3rd Floor  
Montpelier, Vermont 05602

Public Service Board  
State of Vermont  
120 State Street  
Montpelier, Vermont 05602

Chairman, Board of Selectmen  
Town of Vernon  
Post Office Box 116  
Vernon, Vermont 05354-0116

Mr. J. P. Pelletier, Vice President  
Vermont Yankee Nuclear Power  
Corporation  
Ferry Road  
Brattleboro, Vermont 05301

Mr. Robert J. Wanczyk, Plant Manager  
Vermont Yankee Nuclear Power Plant  
P. O. Box 157, Governor Hunt Road  
Vernon, VT 05354

G. Dana Bisbee, Esq.  
Office of the Attorney General  
Environmental Protection Bureau  
State House Annex  
25 Capitol Street  
Concord, New Hampshire 03301-6937

Resident Inspector  
Vermont Yankee Nuclear Power Station  
U.S. Nuclear Regulatory Commission  
P. O. Box 176  
Vernon, Vermont 05354

Chief, Safety Unit  
Office of the Attorney General  
One Ashburton Place, 19th Floor  
Boston, Massachusetts 02108

Mr. David Rodham, Director  
Massachusetts Civil Defense Agency  
400 Worcester Rd.  
P.O. Box 1496  
Framingham, Massachusetts 01701-0317  
ATTN: James Muckerheide

Mr. Raymond N. McCandless  
Vermont Division of Occupational  
and Radiological Health  
Administration Building  
Montpelier, Vermont 05602

Mr. L. A. Tremblay  
Senior Licensing Engineer  
Vermont Yankee Nuclear Power  
Corporation  
580 Main Street  
Bolton, Massachusetts 01740-1398