

RECEIVED
NRC

Southern California Edison Company

1983 APR -4 AM 8:54

SCE

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

REGION V

TELEPHONE
(714) 492-7700

H. B. RAY
STATION MANAGER

March 29, 1983

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator


Dear Sir:

Subject: Docket No. 50-361 and 50-362
30-Day Report
Licensee Event Report No. 83-023 (Docket 50-361)
San Onofre Nuclear Generating Station, Units 2 & 3

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating Licenses NPF-10 and NPF-15 for San Onofre Units 2 and 3, respectively, this submittal provides the required 30-day written report and a copy of Licensee Event Report (LER) 83-023 addressing an occurrence involving Limiting Condition for Operation (LCO) 3.3.2 associated with the Toxic Gas Isolation System (TGIS). Since this occurrence involves a shared system between Unit 2 and Unit 3, in accordance with NUREG 0161, a single LER for Unit 2 (Docket 50-361) is enclosed.

If there are any questions regarding this event, please contact me.

Sincerely,



Enclosure: LER 83-023

8304110177 830329
PDR ADOCK 05000361
S PDR

IC-22
83-148

March 29, 1983

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)
R.J. Pate (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)