

APPROVED BY OMB
3150-0011
EXPIRES 4-30-82

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1		s	c	v	c	s	l	(2)	0	0	-	0	0	0	0	-	0	0	(3)	4	1	0	0	0	(4)			(5)	
7	8	9	LICENSEE CODE						14	15	LICENSE NUMBER										25	LICENSE TYPE					30	CAT. 35		

0 1 7 8

REPORT SOURCE

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOCKET NUMBER

EVENT DATE

REPORT DATE

On March 9, 1983, with the Plant in Mode 1, the Main Control Board pressure indicator for Reactor Building Pressure Channel 950 failed low. Similar failures have occurred to this channel on December 2, 1982 (LER 82-016) and February 3, 1983 (LER 83-009). All of the failures are attributed to the same component failure. There were no adverse consequences during this event since the remaining three (3) channels of Reactor Building Pressure remained operable.

08																				80			
7		6		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE								COMP. SUBCODE		VALVE SUBCODE			
09		7		8		I B 11		E 12		E 13		I N S T R U 14								T 15		Z 16	
9		10		11		12		13		14		15		16		17		18		19		20	
17		LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		18		19		20		21		22	
18		19		20		21		22		23		24		25		26		27		28		29	
30		31		32		33		34		35		36		37		38		39		40		41	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER		42		43		44	
Z 18		C 19		Z 20		Z 21		000 22		Y 23		N 24		N 25		B08 26		45		46		47	
33		34		35		36		37		38		39		40		41		42		43		44	

1 0 | The cause is attributed to the intermittent failure of pressure transmitter

1 1 | PT-950. The transmitter output returned to normal after the channel was placed in

1 2 | the bypassed condition. The channel was returned to operable status on March 9,

1 3 | 1983, upon the completion of a surveillance test. The transmitter is presently

1 4 | being replaced to prevent recurrence.

FACILITY STATUS (1) 5 (28) 0 5 0 (29) N/A (30)
 METHOD OF DISCOVERY (31) A Operator Observation (32)
 ACTIVITY CONTENT RELEASED OF RELEASE (33) 2 (34) 5 N/A (35)
 LOCATION OF RELEASE (36) N/A
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (37) 0 0 0 (38) 2 (39) N/A
 PERSONNEL INJURIES NUMBER DESCRIPTION (40) 0 0 0 (41) N/A
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (42) 2 (43) N/A
 PUBLICITY ISSUED DESCRIPTION (44) N (45) N/A
 8304130231 830408
 PDR ADOCK 05000395
 S PDR
 NRC USE ONLY

PHONE:

(803) 345-5209