

1807
PUBLIC

SEP 14 1994

Michigan State University
ATTN: Arnold Revzin, Ph.D.
Associate Vice President
for Research Services
232 Hannah Administration Building
East Lansing, MI 48824

License No. 21-00021-30
Docket No. 030-06956

Dear Dr. Revzin:

This refers to the routine safety inspection conducted by Thomas Young of this office on July 11-15, 1994, of activities authorized by NRC Byproduct Material License No. 21-00021-30, and to the discussion of our findings with you and your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities were found to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosure, and your response to this letter will be placed in the NRC Public Document Room.

The response directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by John A. Grobe

John A. Grobe, Chief
Nuclear Materials Inspection
Section 2

Enclosure: Notice
of Violation

cc w/enclosure:
Kristin Erickson, RSO

bcc w/enclosure:
PUBLIC

RIII
TH Young
Young/bt
08/25/94

260030

RIII
GROBE
Grobe
08/12/94