

ENCLOSURE 1

NOTICE OF VIOLATION

Duke Power Company  
McGuire Units 1 and 2

Docket Nos. 369, 370  
License Nos. NPF-9, NPF-17

During an Nuclear Regulatory Commission (NRC) inspection conducted from July 17, 1994, through August 20, 1994, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violation is listed below:

Technical Specification 6.8.1, requires that written procedures be established, implemented and maintained covering the activities in the applicable procedures recommended in Appendix A of Regulatory Guide 1.33, Revision 2, 1978. Operations Management Procedure 5-3, Technical Specification Action Items Logbook, requires that control room personnel review all necessary documents to ensure that all necessary tasks are completed before equipment is declared operable. Work order package 94026627, Task 3, required that operations personnel perform a retest of the 2B2 sump pump following the completion of a periodic test.

Contrary to the above, on August 16, 1994, control room personnel failed to verify that operations personnel had performed the required retest of the 2B2 diesel generator sump pump before they declared it operable and removed the 2B3 sump pump from service, thereby rendering the 2B emergency diesel generator inoperable.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Duke Power Company is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region II, a copy to the NRC Resident Inspector, at McGuire Nuclear Station, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order or demand for information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Atlanta, Georgia  
this 19th day of September 1994