

APPENDIX A

NOTICE OF VIOLATION

Department of the Navy
Long Beach Naval Shipyard
Long Beach, California 90822

License No. 04-06145-01

As a result of the inspection conducted during January 17-18, 1983, and in accordance with the NRC Enforcement Policy, 10 CFR Part 2, Appendix C, the following violations were identified:

- A. 10 CFR 34.24 requires that radiation survey instruments be calibrated at intervals not to exceed three months.

Contrary to the above requirement, since the last inspection on February 10, 1982 until this inspection on January 17-18, 1983 the licensee was calibrating all radiation survey instruments used by radiographers at six month intervals.

This is a Severity Level IV Violation (Supplement VI).

- B. License Condition 15 states that the licensee shall possess and use licensed materials in accordance with statements, representations, and procedures contained in the application dated June 2, 1978. The licensee's Administrative, Operating, and Emergency Procedures, Chapter 1, paragraph 4.a(3)(c), provided as part of the June 2, 1978 application, states that management will perform annual audits of radiographic and radiac operations.

Contrary to the above requirement, no annual management audit was performed of radiographic or radiac operations during the calendar year of 1982.

This is a Severity Level IV Violation (Supplement VI)

- C. License Condition 15 states that the licensee shall possess and use licensed materials in accordance with statements, representations, and procedures contained in application dated June 2, 1978. The licensee's Administrative, Operating and Emergency Procedures, paragraph 3.b(1)(e) submitted as part of the June 2, 1978 application states that each new shipyard employee will be trained and certified in accordance with paragraphs 3.b(1)(c), and 3.b(1)(d) prior to performing industrial radiography. Paragraph 3.b(1)(c) requires that formal classroom and equipment training as outlined in paragraph 3.b(3), be provided and that an examination covering these subjects be given.


Contrary to the above requirements, at the time of the inspection, several employees had performed industrial radiography and had not received the formal classroom and equipment usage training as outlined in paragraph 3.b(1)(c) of the Administrative, Operating, and Emergency Procedures.

This is a Severity Level V Violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Long Beach Naval Shipyard is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

APR 8 1983

Dated



R. D. Thomas, Chief
Materials Radiation Protection Section