

DMB

SAFETY INSPECTION

1. LICENSEE Apache Inspection Service, Inc. P.O. Box 944 Elk City, OK 73644		2. REGIONAL OFFICE U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012	
3. DOCKET NUMBER(S) 30-19464	4. LICENSE NUMBER(S) 35-19884-01	5. DATE OF INSPECTION April 13, 1983	

Licensee:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission's (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

1. Within the scope of this inspection, no violations were observed.

2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.

3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements.
THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11.

A. _____ was not properly posted to indicate the presence of a _____ 10 CFR 20.203(b), (c), (d), (e) or 34.42.

B. Containers located in _____ were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2).

C. Leak tests of sealed sources were not performed at the proper frequencies. 10 CFR _____ License Condition Number 13

D. Records of radiation surveys were not properly maintained. 10 CFR _____ or License Condition Number 17

E. Documents were not properly posted or otherwise made available. 10 CFR 19.11.

F. Reports or notifications of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____



H. _____

I. _____

J. _____

K. 8305030367 830413
NMS LIC30
35-19884-01 PDR

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

 SIGNATURE - LICENSEE	<u>4-12-83</u> DATE	 SIGNATURE - NRC INSPECTOR	<u>4/13/83</u> DATE
--	------------------------	---	------------------------

IE07

NRC FORM 700 A <small>(11-83) 16 MC 0535</small> INSPECTOR'S REPORT (Continuation) Office of Inspection and Enforcement	DOCKET NO (8 digits) OR LICENSE NO (BY PRODUCT) (13 digits)		REPORT NO SEQ		MODULE NUMBER		5 7 7 7 1 0 B 6	VIOLATION SEVERITY OR DEVIATION D	SITE RELATED						
	3 5 - 1 9 8 8 4 - 0 1		8 3 0 1		A					1 2 3 4 5 6 X	<input type="checkbox"/>	<input type="checkbox"/>			
					B								7 8	<input type="checkbox"/>	<input type="checkbox"/>
					C										
				D		10	<input type="checkbox"/>	<input type="checkbox"/>							

VIOLATION OR DEVIATION (Enter up to 2400 characters for each item. If the text exceeds this number, it will be necessary to paraphrase. Limit lines to 50 characters each.)

1	
2	Contrary to License Condition 17, records of radiation surveys
3	
4	were not properly maintained.
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	

