



**SMUD**

SACRAMENTO MUNICIPAL UTILITY DISTRICT ☐ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211  
RPO 83-69

May 2, 1983

J B MARTIN, REGIONAL ADMINISTRATOR  
REGION V OFFICE OF INSPECTION AND ENFORCEMENT  
U S NUCLEAR REGULATORY COMMISSION  
1450 MARIA LANE SUITE 210  
WALNUT CREEK CA 94596

DOCKET NO. 50-312  
LICENSE NO. DPR-54  
SPECIAL REPORT NUMBER 83-02

In accordance with Rancho Seco Nuclear Generating Station Technical Specifications Section 6.9.5.E, the Sacramento Municipal Utility District hereby submits Special Report 83-02.

On March 26, 1983, the Motor Driven Fire Pump, P-440, was administratively taken out of service due to the necessity to drain the Cooling Tower circulating water basin during the current outage. Technical Specification 3.14.2.2 requires an inoperable fire pump to be returned to operable status within seven days or a special report is required within the next thirty days. This report fulfills the requirement of that specification.

Since the pump is only administratively out of service, a recovery procedure for the pump was established. This procedure involves filling the fire pump basin by opening an inlet bypass valve, PCW-002, from the plant cooling water system which would provide sufficient water for the pump to operate. The pump would then be manually operated as needed.

This procedure will remain in place until the circulating water basin is filled and the motor driven pump is placed in service. The diesel driven pump is operable to provide water for the fire protection system in an automatic mode.

*W. K. Latham*

W. K. Latham  
Acting General Manager

cc: Director, NRR

8305130160 830502  
PDR ADOCK 05000312  
S PDR

TE-22