

**UNITED STATES ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE**

<p>1. LICENSEE SAXTON NUCLEAR EXPERIMENTAL CORP. P.O. Box 542 Reading, Pennsylvania</p>	<p>2. REGIONAL OFFICE U.S. ATOMIC ENERGY COMMISSION Region I, Division of Compliance 376 Hudson Street New York, New York 10014</p>
<p>3. LICENSE NUMBER DPR-4</p>	<p>4. DATE(S) OF INSPECTION April 16 & 17, 1964</p>

5. The following activities under your license (identified in Item No. 3 above) appear to be in noncompliance with AEC regulations or license requirements, as indicated.

- a. Paragraph 3 of SNBC Operating License No. DPR-4 requires conformance to Section 20.203(c) of Part 20 of the Commission regulations. This section requires special safety measures to be taken and warnings to be displayed for all areas in which an individual might receive a dose of 100 mrem in one hour.

On April 17, 1964, our inspector noted that three radioactive waste drums, that were stored in the filled drum storage area, had radiation levels in excess of 100 mrem/hr. The storage area and the cited drums were improperly equipped and incorrectly marked for the observed levels of radiation.

9107150216 910506
PDR FOIA
DEKOK91-17 PDR

APR 21 1964

Supplementary page None attached. JAMES P. O'Reilly APR 21 1964
AEC Compliance Inspector Date

ORIGINAL: LICENSEE. COPIES: CO REGION CO HEADQUARTERS L&R HEADQUARTERS.