

USNRC REGION II  
ATLANTA GEORGIA

83 JUN 3 A12:49

June 1, 1983  
L-83-339

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta St., Suite 2900  
Atlanta, GA 30303

Dear Mr. O'Reilly:

Re: ST. LUCIE UNIT NO. 2  
DOCKET 50-389  
IE BULLETIN 79-02

References: 1) Uhrig to O'Reilly letter, L-79-180, dated July 2, 1979  
2) Uhrig to O'Reilly letter, L-80-19, dated June 14, 1980  
3) Uhrig to Eisenhut letter, L-82-408, dated Sept. 21, 1982

The St. Lucie Unit No. 2 Operating License (NPF-16) Attachment 1, "Items To Be Completed Prior to Exceeding 5% Rated Power", requires that Bulletin 79-02 be complete to the satisfaction of Region II. In order to close out this license condition Florida Power & Light Company (FPL), via this letter, is submitting our final response to this bulletin.

FPL previously reviewed and responded to this bulletin in the referenced letters. This correspondence stated that the overall philosophy at St. Lucie Unit No. 2 was to avoid the use of concrete expansion anchors through the design effort. However, due to design restraints, it was occasionally necessary to use expansion anchors on Category I restraints/hangers. FPL employed stringent design criteria when expansion anchors were used. In addition, a systematic Quality Control program was implemented to ensure proper installation and testing. All safety-related expansion anchors installed to date have been inspected to the criteria of Bulletin 79-02.

It should be noted that continuing construction efforts, although limited, will continue until 5% power (i.e., Appendix "R" work, etc.). If in this effort expansion anchors are used, the present program will be employed. For future plant changes to the operating plant, FPL implemented a process called a Plant Change/Modification (PC/M) procedure which ensures that any future change to expansion anchors will use the criteria outlined in Bulletin 79-02.

8306140581 830601  
PDR ADOCK 05000389  
G PDR


110 IE11

Page 2  
ST. LUCIE UNIT NO. 2  
DOCKET 50-389  
IE BULLETIN 79-02

Region II inspectors have previously inspected our in-process efforts and documentation. All completed documentation to Bulletin 79-02 are maintained at the site.

This letter completes the reporting requirements for Bulletin 79-02.

Very truly yours,

A handwritten signature in cursive script, reading "Robert E. Uhrig". The signature is written in dark ink and is positioned above the typed name.

Robert E. Uhrig  
Vice President  
Advanced Systems and Technology

REU/PPC/rms