

ATTACHMENT TO LER 83-048, REVISION 1

SOUTHERN CALIFORNIA EDISON COMPANY
SAN ONOFRE NUCLEAR GENERATING STATION

UNITS 2 AND 3, DOCKET NO. 50-361

SUPPLEMENTAL INFORMATION FOR CORRECTIVE ACTIONS

However, Quality Assurance will monitor the quality of hydrogen gas purchased from the vendor who supplied the gas determined to have a high impurity level. A vendor audit will be performed during the next quarter with particular attention directed to the purchase order covering the hydrogen bottles. The need for corrective action will be determined based on the results of this continued monitoring and audit.

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION
P.O. BOX 128
SAN CLEMENTE, CALIFORNIA 92672

RECEIVED
NRC

1983 JUN 30 PM 12:26

SCE

REGION VICE

TELEPHONE
(714) 492-7700

H. B. RAY
STATION MANAGER

June 24, 1983

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket Nos. 50-361 and 50-362
Licensee Event Report No. 83-048, Revision 1
(Docket No. 50-361)
San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter, H. B. Ray (SCE) to J. B. Martin (NRC),
dated May 24, 1983

The referenced letter provided you with the required 30-Day written report and a copy of the Licensee Event Report (LER) No. 83-048, pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating Licenses NPF-10 and NPF-15 of San Onofre Units 2 and 3, respectively, addressing an occurrence involving Limiting Condition for Operation (LCO) 3.3.2 associated with the Toxic Gas Isolation System (TGIS). Since this occurrence involved a shared system between Units 2 and 3, a single LER for Unit 2 (Docket 50-361) was provided in accordance with NUREG 0161.

The enclosed Revision 1 to LER 83-048 provides corrective action which will be taken to prevent future recurrence of this incident.

IE-22
83-277

Mr. J. B. Martin

-2-

June 24, 1983

If there are any questions regarding this event, please so advise.

Sincerely,

HB King / NYLmark

Enclosure: LER 83-048, Revision 1

cc: A. E. Chaffee (USNRC Resident Inspector, Units 2 and 3)
R. J. Pate (USNRC Resident Inspector, Units 2 and 3)
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)