

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	3	
7	2	9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	4	
7	8	9

ACT
REL

100

153

NAME OF PREPARER T. S. Rotella

PHONE: (305) 465-3550

USNRC REGION II
ATLANTA, GEORGIA

83 AUG 31 P 1: 57



August 29, 1983
PNS-LI-83-575-1

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 50-389-83-43

ST. LUCIE UNIT 2

DATE OF OCCURRENCE: JULY 30, 1983

TECHNICAL SPECIFICATION 3.1.2.4

2B CHARGING PUMP

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

A handwritten signature in cursive script, appearing to read "J. W. Williams, Jr.", is written over the typed name.

J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PLP/mpc

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 SL

OFFICIAL COPY

TE 22
1/1