

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)01 ALJMF2 000-000000-000 341111 45  
7 8 9 14 15 25 26 30 37 38

CONT

01 REPORT SOURCE L 6 05000364 7 081083 8 090883 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 0130 on 8/10/83, during the performance of FNP-2-STP-80.1 (Diesel Generator 2B  
03 Operability Test), Diesel Generator 2B was declared inoperable when it failed to  
04 start. Tech. Spec. 3.8.1.1, in part, requires Diesel Generator 2B to be operable.  
05 Tech. Spec. 3.8.1.1 action statement requirements were met. Health/safety of the  
06 public was not affected. This is the first failure in the last 100 valid tests.  
07  
08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
E E 11 E 12 B 13 E N G I N E 14 Z 15 Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 LER/NO REPORT NUMBER 8 3 21 22 0 3 3 24 26 0 3 27 28 29 L 30 31 0 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER 26  
A 18 Z 19 Z 20 Z 21 0 0 0 0 0 40 N 23 Y 24 A 25 F 0 1 0 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 No immediate cause for this event could be determined. The diesel was inspected  
11 and successfully test started. Following satisfactory completion of FNP-2-STP-  
12 80.1, Diesel Generator 2B was declared operable at 0529 on 8/10/83. Subsequent  
13 investigation revealed excessive bushing and rotor wear on the #1 starting air  
14 distributor. The distributor was replaced.

15 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32  
E 28 1 0 0 29 NA B 31 Surveillance Test  
7 8 9 10 11 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
Z 33 Z 34 NA NA  
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  
0 0 0 37 Z 38 NA  
7 8 9 10 11 12 13 80

18 PERSONNEL INJURIES NUMBER DESCRIPTION 41  
0 0 0 40 NA  
7 8 9 10 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43  
Z 42 NA  
7 8 9 10 80

20 PUBLICITY ISSUED DESCRIPTION 45  
N 44 NA  
7 8 9 10 80

NAME OF PREPARER W. G. Hairston, III

PHONE: (205) 899-5156

8309190075 830908  
PDR ADOCK 05000348  
S PDR