



GPU Nuclear Corporation  
One Upper Pond Road  
Parsippany, New Jersey 07054  
201-316-7000  
TELEX 136-482  
Writer's Direct Dial Number:  
November 3, 1994

5000-94-0044  
C321-94-2290

U. S. Nuclear Regulatory Commission  
Att: Document Control Desk  
Washington, DC 20555

Gentlemen:

Subject: Oyster Creek Nuclear Generating Station (OCNUS)  
Docket No. 50-219  
Facility Operating License No. DPR-16  
Core Spray Sparger - 15R Outage Inspections

The Oyster Creek Nuclear Generating Station Technical Specifications, Appendix A, para. 6.9.3.e, and the Facility Operating License para. 2.C.(5), require that a special report presenting the results of the inservice inspection of the core spray spargers during each refueling outage be provided for review and that authorization be obtained from the Commission's staff before the plant is restarted from each refueling outage.

Topical Report No. TR-098, which is enclosed for your review, is the core spray sparger inspection report for the Cycle 15 refueling outage. It describes the nondestructive examinations that were performed on the core spray spargers and the associated in-vessel annulus piping. The sparger assemblies and in-vessel annulus piping were inspected utilizing a remote visual (camera) examination supplemented with an optional air test. The report documents that no new relevant indications or anomalies were found and no change in pre-existing conditions were noted since the prior Cycle 14 refueling outage inspection.

If you have any questions or comments on this submittal, please contact Mr. Michael Laggart, Manager, Corporate Nuclear Licensing at (201) 316-7968.

Very truly yours,

*R. W. Keaten*  
R. W. Keaten  
Vice President and Director  
Technical Functions

RWK/RTZ/plp

c: Administrator, Region 1  
Senior Resident Inspector  
Oyster Creek NRC Project Manager

9411090214 941103  
PDR ADDCK 05000219  
PDR

090032

GPU Nuclear Corporation is a subsidiary of General Public Utilities Corporation

*Aool*  
*1/1*