

DCD/DCB

MAY 20 1991

Radiologists, Inc.
ATTN: Roger W. Lambie, M.D.
Radiation Safety Officer
6724 Troost Avenue
Suite 900
Kansas City, MO 64131

License No. 24-20047-01
Docket No. 030-17683

Dear Dr. Lambie:

This refers to the routine safety inspection conducted by Mr. S. J. Mulay of this office on April 25-26, 1991 of activities authorized by NRC Byproduct Material License No. 24-20047-01 and to the discussion of our findings with you via telecom on or about May 8, 1991 and with Dr. Herman and Angie Salter at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described regarding apparent violations found during our February 1989, inspection. We have no further questions regarding these matters.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

William G. Snell, Chief
Nuclear Materials Safety
Section 2

9105240211 910520
REG3 LIC30
24-20047-01 PDR

Enclosure: Notice of Violation

cc w/enclosure:
DCD/DCB (RIDS)

R111 *M*
Mulay/sd
5/17/91
R111
WGS
Snell
5/20/91

0 023
405

DE07